

Annexure D

BUILDING SAFETY CERTIFICATE

No.

Dated: 23-10-2021

It is certified that the existing building **Shri Gulab Rai Montessori School, Dhora Road, Vill Itauwa Beniram, Bithari Chainpur, Bareilly. Uttar Pradesh** (name of the building or premises) at **Vill Itauwa Beniram, Bithari Chainpur, Bareilly. Uttar Pradesh** (address) is having block(s)/Floor(s) as per details below:


Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	2 1	-	-	-	-	-


The building is owned/occupied by.....**Shri Gulab Rai Montessori School** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of (Name of Department/ Govt.) on _____x_____ (date of inspection) in the presence ofx..... (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from.....x..... for a period of.....x.....years in accordance with rule and subject to compliance of the specific conditions as appended.

1. The Above certificate has been already issued by by Executive Engineer, Constuction Division-Building, Public Works Department, Bareilly through his office by letter No. 924/NBC Dated 11-04-2016. (Copy Attached)
2. This certificate is based on above certificate and only in prescribed English format .

Issued onx..... at.....x.....by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.


Executive Engineer
Provincial Division PWD Bareilly
Bareilly


AE