

Annexure D

BUILDING SAFETY CERTIFICATE

No. 36/Camp

Dated: 12-12-2024

It is certified that the existing building **Shri Gulab Rai Montessori School, Dohra Road, Vill Itauwa Beniram, Bithari Chainpur, Bareilly. Uttar Pradesh** (name of the building or premises) at **Vill Itauwa Beniram, Bithari Chainpur, Bareilly. Uttar Pradesh** (address) is having block(s)/Floor(s) as per details below:


Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	3 1	-	-	-	-	-

The building is owned/occupied by..... **Shri Gulab Rai Montessori School** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of UPPWD GOVT.OF UP (Name of Department/ Govt.) on **11-04-2016** (as per previous certificate) (date of inspection) in the presence of Mr. Rajesh Agarwal R/O Z-9/35 Rampur Garden Bareilly. (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **11-04-2016** for a period of 20 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. The Above certificate has been already issued by by Executive Engineer, Constuction Division-Building, Public Works Department, Bareilly through his office by letter No. 924/NBC Dated 11-04-2016. (Copy Attached)
2. This certificate is based on above certificate and only in prescribed English format .

Issued on 12-12-2024 at Bareilly by Assiatant Engineer-I, Provincial Division, PWD, Bareilly.

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.


Assistant Engineer-I
Provincial Divison PWD Bareilly
बरेली
सहायक अभियन्ता
पब्लिक वर्क्स, प्रोविन्सियल
बरेली

CERTIFICATE
(उपविधि संख्या-13.2)

(The certificate to be submitted with the application for building permission along with the building drawings and Building Information Schedule).

1. Certified that the building plans submitted for approval also satisfy the safety requirements as stipulated in the Indian Standard, Codes, guidelines and documents specified in the Annexure-I of the Building Bye-Laws regarding earthquake safety awareness and the information given in the attached Building Information Schedule, is factually correct to the best of my knowledge and understanding.
2. It is also certified that the structural design including safety from natural hazards including Earth Quake has been prepared by duly qualified graduate Civil Engineer along with Post Graduate Diploma or Degree in Structural Engineering from a recognized University.

3. Location/Address of Building

Plot No. Khasra No. 87B, 88B, 89B, 90B, 91B, 92, 99, 100, 101, 102, 103.
Scheme/Colony. Village. Etawa. Benipuram, Bareilly.
Town.....
District.... Bareilly.....

4. Particulars of Building

1. Ground Coverage (sq mt) 3344.36 Sqmt.
2. Total covered area (sq mt) 10346.61 Sqmt.
3. Maximum Numbers of Floors above ground. +2 Floor.

Signature of Owner with date 12/11/14

Signature of the Structural Engineer who had prepared the design with date

Name (Block) RAJESH A. SARWAL
(Block) (MANAGER)

Name En. RAJIB SAXENA

Address :
2-9135 RAMPUR GARDEN
BAREILLY.

Legible Seal: (with address)

Signature of the Architect who had Prepared the design with date

Name (Block) Pawan Bhatt
COA Registration No. CA 1991-2553
Legible Seal (with address)

Post D.D. Post 741
Bareilly.

En. RAJIB SAXENA
B.E. (Civil), MIE, MISE, FIV, FCET
Certified Structural & Chartered Engineer
Member Regd. No. ISE (India) LM-167
IE (India) M-1570964
Mobile 9412604379

SURAJMUKHI COMPLEX
Madhinath
Near B. V. B.
BAREILLY-243001